


FOR BASE AND SHED



S.NO.	MODEL	CANOPY SIZE			APPROX. WEIGHT (Kg.)
		L	B	H	
2	623-825 RWA	2000	1500	1600	1500

NOTES:-

- 1-A DISTANCE OF 1.5 Mtr. SHOULD BE LEFT BEYOND FOUNDATION & FOR PROPER AIR FLOW & OPENING OF DOORS.
- 2-THE HEIGHT OF FOUNDATION BELOW AND ABOVE THE GROUND LEVEL ARE FOR REFERENCE ONLY AS THEY DEPEND UPON NATURE OF EARTH AT SITE.
- 3-THE LEVEL OF TOP SURFACE OF THE FOUNDATION SHOULD BE SUCH THAT NO WATER CAN ENTER THE JOSEET AT ANY TIME.

ALL DIMENSIONS ARE IN MM.
 CLIENT:-
 PROJECT:-
 CONSULTANT:-

DESIGNED BY: J.K.
 CHECKED BY: A.K.
 APPROVED BY: S.K.
 DATE: 28/04/21
 SCALE: X/1

CSH
 C.S. Hobbies (P) Ltd.
 8/16-1/1, SOGA WARD, NEAR CHS
 RICHMOND, (PUNE NORTH), DIST-412402
 URMARANUM-201123

DRIVING NO. CSH-4/16-1-22/5/21/01
 TITLE:-
 8/16-1/1, SOGA WARD
 SO FOUNDATION DETAIL

DATE: 09/05/2021
 1 OF 1

SPECIFICATION FOR IRON BASE / SHED OF GENSET

IRON BASE FOR GENSET		
S. NO.	ITEMS	QTY
01	Guarder 20ft Length, 6 Inch Height& 3 Inch Thickness	03
02	Labour	—
SHED FOR GENSET 8ft In Height (Via From Base To Top)		
S. NO.	ITEMS	QTY
01	3'' Square Pipe , 20ft	07
02	2'' Square Pipe , 20ft	08
03	Iron Angle	05
04	CJI Sheet	06
06	Lock Handle And Hinges	01
05	Labour	
MUD MAT (IF REQUIRED)		
PAINT JOB		
S. NO.	ITEMS	QTY
01	Redoxide for Base And Shed	10 LTR
02	Paint	8 LTR
CRANE AND LIFTING CHARGES		
S. NO.	ITEMS	QTY
01	For 1 Day	—
FENCING		
S. NO.	ITEMS	QTY
01	FENCING FOR SHED	175 KG

SPECIFICATION FOR EARTHING / WIRING OF GENSET

EARTHENING OF GENSET		
S. NO.	ITEMS	QTY
01	Rods and Chemical Bags	04
02	Labour Charges	_____
WIRING FOR EARTHENING AND POWER TO MAINS SUPPLY		
S. NO.	ITEMS	QTY
01	16mm Copper Wire For Earthing	30 MTR
02	4 Core Alumunium Wire For Mains Power Supply	100 MTR
03	Earthing Bolt	12